

<u>Test Report</u>

NUMBER : TSNH00287208 Applicant : Qingdao Halftone Craft Co.,Ltd Date : Oct 31,2018 Attn :Ms Li Sample Description: One (1) submitted sample said to be **Jewelry**. (STAINLESS STEEL ROD BASE MATERIAL) **Tested Component Of** : Silver color plating metal column casting. Submitted Sample ***** **Tests Conducted:** As requested by the applicant, for details refer to attached page(s) ***** To be continued

Authorized By : For Intertek Testing Services (Tianjin) Ltd. Qingdao Branch

David Zhang Senior Manager



Tel +86 532 8099 3788 Fax +86 532 8096 1802 www.intertek.com.cn www.intertek.com





<u>Test Report</u>

1. Total Lead (Pb) Content

NUMBER : TSNH00287208

With reference to US EPA method 3050B / 3051, acid digestion method was used and total lead content was determined by flame atomic absorption spectrometry.

Tested Sample	Result In ppm	Applicant Requirement In ppm
Tested Component Of Submitted Sample	17	100

ppm =parts per million = mg/kg based on dry weight

2. Total Cadmium (Cd) Content

As per client's request, acid digestion method was used and total cadmium content was determined by flame atomic absorption spectrometry.

Tested Sample	Result In ppm	Applicant Requirement In ppm
Tested Component Of Submitted Sample	<5	100

ppm = parts per million = mg/kg based on dry weight < = less than

Date Sample Received : Oct 26,2018 Testing Period : Oct 26,2018 To Oct 31,2018

To be continued

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct.

Tel +86 532 8099 3788 Fax +86 532 8096 1802 www.intertek.com.cn www.intertek.com





Test Report

Photo

NUMBER : TSNH00287208



End of report

Intertek Testing Service (Tianjin) Ltd., Qingdao Branch 大祥(大津)质量技术服务有限公司 青岛分公司 Building 11, No. 177, Zhuzhou Road, Laoshan District, Qingdao, 266000 China 青岛市崂山区株洲路177号11号楼 邮编266000 Tel +86 532 8099 3788 Fax +86 532 8096 1802 www.intertek.com.cn www.intertek.com

